

Content

1	Introduction	1
2	Problem description	1
3	Examination	2
4	Conclusion	3
5	Measures	3

1 Introduction


This application note describes the effects if the motor cable shield is not connected to the control cabinet back panel or the intended shield connection point on the servo drive. It is intended for users of the servo drives of the smartServo BL 4000-C and ARS 2000 series.

⚠ DANGER ⚠ Life-threatening voltage on motor cable

If the motor cable shield is not connected correctly, there may be danger to life! Furthermore, personal injury and damage to the servo drive may occur.

2 Problem description

During the commissioning phase, it may happen that motor cables are not earthed as intended. The following pictures from the field serve as examples.




This setup contains the following faults:

- The shield of the motor cable is neither stripped nor fixed with a shield clamp **1**
- Motor and encoder cables are fixed with a common shield clamp **2**
- The unshielded part of the motor cables is much too long **3**

The following faults can be seen in this setup:

- The shield clamp is mounted on an anodised mounting profile and not as intended on the servo drive mounting plate **4**
- The shield clamp is not mounted electrically conductive **4**
- The motor shield should instead be placed on the mounting plate with a large conductive surface **5**



3 Investigation


For the investigation, a set-up with a BL 4304-C was created in the laboratory of Metronix. In this set-up, the faulty earthing described above was simulated. For this purpose, the motor cable shield was disconnected at the Weidmüller plug X6, so that the motor cable shield was not connected to the controller. The measurement was made on the brake control lines that were not connected to the servo drive. However, it is generally valid for all lines that are included in the motor cable. The motor cable used corresponded to the given specification but was extended to 30m to simulate more unfavourable conditions.

The encoder cable was replaced by a dummy encoder. Thus, no current can be discharged via the shield of the encoder cable. The motor itself is not earthed when the power unit is switched on.

With an enabled power stage, the following voltages were measured:


Shielding not connected to the Weidmüller connector, i.e. **no** conductive connection via the motor cable.

Complete shield connection via encoder cable and motor cable.



CH4 (green) Line 5
CH1 (blue) Line 1
CH2 (Light blue) Line 8

Disturbances with approx. 290V amplitude! Danger to life!



CH4 (green) Line 5
CH1 (blue) Line 1
CH2 (Light blue) Line 8

Interference with approx. 2.4V amplitude: OK.

Figure 1: Measurements of the voltage on lines in the motor cable (30m) with incorrect earthing of the cable shield (left) and correct earthing of the cable shield (right).

4 Conclusion

If the wiring is done correctly and completely according to the instructions in the manual, the PWM-related leakage currents can be discharged to earth and no high voltages will occur. Only if the motor cable shield is correctly connected to the control cabinet rear panel and all instructions for safe electrical installation in the mounting instructions or the manual are followed, high voltages in the other lines and on the cable shield will be avoided.

5 Measures

⚠ DANGER ⚠ Life-threatening voltage

Always make a good conductive connection between the motor shield and the servo drive housing before switching on the power stage in order to avoid high voltages on lines carried in the motor cable (brake, motor temperature).

Before the very first commissioning, follow all instructions in the section *Electrical Installation*, especially all instructions in the section *Proper Wiring* of the BL 4000-C Product manual.

> BL 4100-C




Figure 2: Connection of the motor shield with the BL 4100-C

> BL 4300-C




Figure 3: Connection of the motor shield with the BL 4300-C

INFORMATION Also applies to ARS 2000 FS

The connection instructions also apply in the same way to the connection of the motor cable shield on ARS 2000 FS series devices.

Original Application note

> Copyright

© 2022 Metronix Meßgeräte und Elektronik GmbH. All rights reserved.

The information and data in this document have been composed to the best of our knowledge. However, deviations between the document and the product cannot be excluded entirely. For the devices and the corresponding software in the version handed out to the customer, Metronix guarantees the contractual use in accordance with the user documentation. In the case of serious deviations from the user documentation, Metronix has the right and the obligation to repair, unless it would involve an unreasonable effort. A possible liability does not include deficiencies caused by deviations from the operating conditions intended for the device and described in the user documentation. Metronix does not guarantee that the products meet the buyer's demands and purposes or that they work together with other products selected by the buyer. Metronix does not assume any liability for damage resulting from the combined use of its products with other products or resulting from improper handling of machines or systems. Metronix reserves the right to modify, amend or improve the document or the product without prior notification.

This document may, neither entirely nor in part, be reproduced, translated into any other natural or machine-readable language nor transferred to electronic, mechanical, optical or any other kind of data media, without the express authorization of the author.

> Contact

Metronix Meßgeräte und Elektronik GmbH

Kocherstraße 3

38120 Braunschweig

Germany

Telefon: +49(0)531 86680

Telefax: +49(0)531 8668555

E-mail: vertrieb@metronix.de <https://www.metronix.de>

> Revision information

Document title	Application Note 122
Filename	APPL122_Effects_of_missing_earthing_of_the_motor_cable_shield_EN.docx
Version	1.0
Year	2022